


Invisible Tuner Assembly Instructions

Step 1: Headstock Processing


Please follow the marked dimension to process the headstock.



Step 3: Solder the LED Light Pipe and the main engine together

As Picture 6 shown: RED – 1st String, YELLOW – 2nd String, GREEN – 3rd String, BLACK -- 4th String, WHITE – 5th String, Transparent – 6th String.


Note: As Picture 7 shown, solder the yellow thread to the soldering pad "R", red thread to soldering pad "+", green thread to soldering pad "G".



Step 2: LED Light Pipe Assembly

Distinguish the LED light pipe according to the colors of its wire: RED – 1st String, YELLOW – 2nd String, GREEN – 3rd String, BLACK -- 4th String, WHITE – 5th String, Transparent – 6th String.

Note: The Positioning direction of LED light pipe should be same with the positioning direction of the headstock slot.



Step 4: The Main Engine Assembly

Screw the accessory screws in the corresponding holes.

